



Duke Power 526 South Church St. Charlotte, NC 28202 Mailing Address: EC13K / P. O. Box 1006

Charlotte, NC 28201

January 20, 2005

NC Department of Environment and Natural Resources Division of Waste Management 610 East Center Avenue – Suite 301 Mooresville, NC 28115

NC DEPT. OF ENVIRONMENT AND NATURAL RESOURCES RECEIVED

JAN 2 4 2006

Attention:

Ms. Teresa Bradford Solid Waste Section

MOORESVILLE REGIONAL OF FICE DIVISION OF WASTE MARKAGEMENT, PAYS

Subject:

Duke Power - Marshall Steam Station

Solid Waste Permit 18-04 Repairs to Landfill Erosion

Dear Ms. Bradford,

In July 2005, Duke Power contacted you regarding erosion issues at our ash landfill at the Marshall Steam Station. In our discussions, you requested that Duke Power only use clean fill to make repairs and also requested that a brief follow-up report documenting the repairs be prepared and submitted to your attention. This letter is being submitted to meet your requirement for a follow-up report.

In summary, upon discovery of erosion issues associated with failed slope drains, Duke Power took the following actions:

- Repaired erosion problems and replaced the failed corrugated metal piping associated with slope drains on the east side of the landfill. The piping was replaced with corrugated smoothwall push joint piping (ADS N12 Solid-Ultra (IB) pipe).
- Repaired all inlets and outlets associated with the above-referenced piping and graded and seeded the disturbed areas.
- Re-established approximately 500 linear feet of ditch on the east side of the landfill to improve drainage.
- Repaired and improved the road that accesses the top of the landfill.

T. Bradford - NCDENR Page 2 January 20, 2006

Based on the work we have done, Duke Power is confident that the upgraded piping and other repairs made will minimize any future erosion issues. If you have any questions or require additional information, please feel free to contact me at (704) 382-7161.

Sincerely,

Patrick J. McCabe, PE

Environmental Support